



MCD

ZA de l'Arceau
49300 LE PUY SAINT BONNET
Tel : 02 41 56 46 00
www.mcd-fr.com

Au Puy, Le 18 Avril 2008

To the technical department

Object: Modifications N° 1 « locking striker modifications ».

Dear customer,

We want to inform you about the locking striker's modifications.


In fact, some MCD's users spoke about the difficulty they have to open shutters with double handle. They must constrict the bottom seal to open without difficulty their shutters.

We identify the problem and do the modifications: We have changed the opening radius and the depth on the locking striker creating a new mould. (*cf. Picture number 1 and 2*)

From today, you will have no difficulty to open the shutters with double handle.

Best regards.

MCD's team



Picture number 1
Old locking striker

Picture number 2
New locking striker